



The PROPLAST "PRO-CONTROL" 50 141 012 is necessary for recognizing of Direction Indicator failure.

If there are messages for Tail light and Brake light failure, please use load resistors like PROPLAST 50 125 012 and 50 139 012 parallel to the function with problems. Be aware that failure recognizing of this functions will be switched off in that case.

The "PRO-CONTROL" as well as the PROPLAST devices 50 125 012 and the 50 139 012 have to be mounted on a metal surface in order to dissipate the incurring heat!

Attention!! As automobile manufacturers constantly adjust the electronic systems of their vehicles, we cannot grant any warranty on our LCG concerning functionality.

Connection of LED Tail Lamps using PRO-CONTROL

Dokument:	Version 12V	REV:	A3
Datum:	15.11.2012	Blatt:	1/1
Autor:		Kunststofftechnik Jedermann GmbH	